

# ACO DRAIN

## Clifton Hill Niagara Falls, ON



### ACO PORTFOLIO

#### Product:

#### *FG200 with ADA ductile iron grates*



Rain water was causing a hazard for both pedestrians and motorists at Clifton Hill in Niagara Falls.

Due to the steep incline, engineers were having difficulty finding a drainage system that could intercept the heavy rain fall. To solve the problem, ACO's FG200 fiberglass trench drain system was installed for its large hydraulic capacity and long run capabilities.

By using ADA compliant ductile iron grates, tourists were able to cross the trench drain safely, while the Load Class E rating provided the strong grates needed to withstand vehicular traffic.

Due to the success of the first installation, three more FG200 runs are installed in other areas of Clifton Hill.